

LAKE BURLEY GRIFFIN

Lake Wall Renewal



Rock and stone lake wall strengthened



1.5m deep holes drilled behind walls for resin injection



Ground Penetrating Radar scans



Trip hazards to be repaired along RG Menzies and Lennox Gardens by end of September



and 1 day

Time in which injection works were completed



Resin used through to the end of August

1.85km

Wall surveyed in detail to allow accurate ongoing condition monitoring



Dead trees removed



New trees planted



Australian Government
National Capital Authority