

WEST BASIN STAGE 2 - LAND RECLAMATION AND BOARDWALK
SUMMARY OF TREES TO BE REMOVED

Tree Number	Regulated Tree	Registered Tree	Arboricultural Assessment	Urban Amenity Assessment	Species	Common Name	Height	Tree Canopy	Trunk Circumference	Trunk Dia.	Qty in Group	Comments
1041	N	No	P	L	Eucalyptus mannifera	White brittle gum	6	4	500	0.02	1.00	Nothing to note
1053	Y	No	M	H	Eucalyptus mannifera	White brittle gum	15	9	1300	0.02	1.00	Nothing to note
1054	Y	No	M	H	Eucalyptus mannifera	White brittle gum	16	9	1300	0.02	1.00	Nothing to note
1111	Y	No	P	L	Pinus ponderosa	Bull Pine	18	14	2100	0.02	1.00	Infected by Lophodermium sp.
1112	Y	No	P	L	Pinus ponderosa	Bull Pine	16	14	2100	0.02	1.00	Infected by Lophodermium sp.
1140	N	No	P	L	Betula pendula	Silver Birch	9	6	850	0.02	1.00	Nothing to note
1141	Y	No	P	M	Salix babylonica	Weeping Willow	16	14	2800	0.02	1.00	Rot at 2m and 4m with bees
1768	N	No	P	L	Casuarina cunninghamiana	River Sheoak	10	9	1100	0.34	1.00	Nothing to note
G06	Y	No	M	M	Salix sp.	Willow					5	Weed species
G08	Y	No	M	M	Populus nigra 'Italica'	Lombardy poplar					39	Nothing to note
G18	N	No	M	M	Prunus cerasifera	Cherry Plum					16	Nothing to note
G19	Y	No	M	H	C.cunninghamiana/ P. nigra	River Sheoak					16	Nothing to note
G20	Y	No	P	M	S.babylonica /F.oxycarpa	Weeping Willow					20	Very near water edge
										Total	104	